













L64 Skill Parts List

1  Top 1 PC	2  Basket 1 PC	3  Base 1 PC	4  Top Pole 1 PC	5  Bottom Pole 1 PC	6  M8 x65mm Bolt 3 PCS
7  M8x55mm Bolt 1 PC	8  Allen Tool 1 PC	9  M8x6mm Bolt 3 PCS	10  Hand Wrench 1 PC	11  M8 Nut 4 PCS	12  Plastic Cover 1 PC

Materials: Powder Coated Steel Basket, HDG Steel Center Pole, Powder Coated Steel Base, Zinc Plated Steel Chains

Assembly Instructions

- 01 Assemble the bottom pole (5) to the base (3) and tighten using the nut (11) and bolt (6). Insert the tension bolt (9) and tighten it.
- 02 Assemble the basket (2) to the bottom pole (5) using the nut (11) and bolt (6).
- 03 Assemble the Top Pole (4) into the Bottom Pole (5) using the nut (11) and bolt (7).
- 04 Assemble the Top Assembly (1) with the Top Pole (4) using the nut (11) and bolt (6). Insert the tension bolt (9) and tighten it.
- 05 Finish up by placing the Top Cap (12) into the top of the basket.

